




Therm

SINGLE ZONE WIRING (MULTI-PORT MANIFOLD)



Here is a simple wiring diagram for a Multi-port manifold supplying a single zone with heatmiser PRT. Does not effect the function of other 2 port or 3 port zone valves, neither does the other zones calling for heat effect this ufh zone from working.

EXPLORE THE *Warmth*